General Environmental Incident Summary

Incident: 1376 Date/Time Notice: 3/18/2011 1248 DEM Incident No:

Responsible Party: Bismarck Aero Center

Date Incident: 3/18/2011 Time Incident: 1100 Duration: 1 hours

 County:
 Burleigh
 Twp:
 138
 Rng:
 80
 Sec:
 0
 Qtr:

 Lat:
 46.76567
 Long:
 -100.77370
 Method:
 Derived from Twp Rng

Location Description: 2301 University Drive, Bismarck, ND 58504- This release occured at

Bismarck Airport; AH - 10/16/2012 - Could be Section 10, 14, 15, 23.

Submitted By: Melissa Galvan Peterson Affiliation:

Address:

City: State: Zip:

Received By:

Contact Person: Melissa Galvan Peterson

2301 University Drive, Bldg 17

Bismarck, ND 58504

Distance Nearest Occupied Building:

Type of Incident: FBO was siphoning out excess water and water contained jet fuel out of

containment area of fuel farm

Description of Released Contaminant: Jet Fuel

Volume Spilled: Ag Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident:

Local FBO was siphoning out excess water due to snow melt from their containment area in the fuel farm. The pump ran for approximately an hour. Jet fuel was aborbed by snow pile and therefore was also released during the siphoning out of the containment area. An unknown amount was released into the dirt but a dirt berm was constructed to prevent the contamination of ground water/navigable waters.

Risk Evaluation:

None- dirt berm preventing the jet fuel from reaching ground water/storm drains/navigable waterways.

of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

None once berm constructed and soil contamination removed.

Action Taken or Planned:

Airport Management discovered situation and immediately ceased the pumping, created the dirt berm, and contacted appropriate authorities. Upon direction from the State Department of Health, the Airport will take further action to remove contaminated soil.

Wastes Disposal Location: At approved disposal site.

Tuesday, March 15, 2016 Page 1 of 2

Agencies Involved: Local Emergency Manager, Airport Fire Department

U	p	d	a	te	S
---	---	---	---	----	---

Date: 3/31/2011 Comment Author: Grosz, Joe

Updated Volume:

Notes:

Meet with Melissa Galvan, Timothy Thorsen , and Jon Simmers. Advised that once the snow melts and ground thaws to take some soil samples and then will advise off of the analytical results

Date: 6/28/2011 Comment Author: Grosz, Joe

Updated Volume:

Notes:

Received the analytical results and the remediation is good. We have decided that no further action is needed. Letter stating this will be sen to Tim Thorsen tomorrow.

Tuesday, March 15, 2016 Page 2 of 2